UNITY Mining Limited

Progress Photos

Dargues Gold Mine

Majors Creek, NSW

14 March 2013

Construction of primary site access road, looking west from Majors Creek Road.

Progress Photos
Dargues Gold Mine
Majors Creek, NSW
14 March 2013

On the road to production……

Earthworks in the box cut.

Progress Photos
Dargues Gold Mine
Majors Creek, NSW
14 March 2013

On the road to production……

Earthworks at the opening of the box cut looking north.

Progress Photos
Dargues Gold Mine
Majors Creek, NSW
14 March 2013

On the road to production……

Looking south over ROM pad earthworks.

Progress Photos
Dargues Gold Mine
Majors Creek, NSW
14 March 2013

On the road to production……

Looking east over ROM pad with plant site on left.

Spring Creek in middle ground.

On the road to production……

Progress Photos
Dargues Gold Mine
Majors Creek, NSW
14 March 2013

Granite “floater rocks” for relocation to main mine entrance gate.

Progress Photos
Dargues Gold Mine
Majors Creek, NSW
14 March 2013

On the road to production……

Looking NW across start of box cut from ridge at west end of Dargues.

Start of box cut is just beyond ridge in middle ground.

On the road to production……

Progress Photos
Dargues Gold Mine
Majors Creek, NSW
14 March 2013